

GM ANNOUNCES SIX RECALLS, JUNE 30, 2014

#	MY/MODELS	CONDITION	U.S. POPULATION	GMNA POPULATION
1	1997-2005 Chevrolet Malibu; 1998-2002 Oldsmobile Intrique; 1999-2004 Oldsmobile Alero; 1999-2005 Pontiac Grand Am; 2000-05 Chevrolet Impala and Monte Carlo; 2004-08 Pontiac Grand Prix	Unintended ignition key rotation	6,805,679	7,610,862
2	2003-14 Cadillac CTS, 2004-06 Cadillac SRX	Unintended ignition key rotation	554,328	616,179
3	2011-14 Chevrolet Cruze; 2012-14 Chevrolet Sonic; 2013-14 Chevrolet Trax, Buick Encore and Verano	On certain vehicles, insulation on the engine block heater power cord (if equipped) may become damaged during very cold conditions.	2,990	20,134
4	2014 Chevrolet Camaro and Impala, Buick Regal, Cadillac XTS	Some vehicles may not have had a “Superhold” joint fastener torqued to specification at the assembly plant.	106	117
5	2007-11 Chevrolet Silverado HD, GMC Sierra HD equipped with an auxiliary battery	An overload in the feed may cause the underhood fusible link to melt due to electrical overload, resulting in potential smoke or flames that could damage the electrical center cover and/or the nearby wiring harness conduit.	9,371	12,008
6	2005-07 Buick Rainier, Chevrolet TrailBlazer, GMC Envoy, Isuzu Ascender, Saab 9-7x; 2006 Chevrolet TrailBlazer EXT, GMC Envoy XL	A possible electrical short in the driver’s door module that could disable the power door lock and window switches and, in rare cases, overheat the module.	181,984	188,705
			U.S. TOTAL	GMNA TOTAL
			7,554,458	8,448,005